

# IRIS USB Reflasher

Software 13.0.0

## Table of Contents

1	Overview .....	3
2	Changes in this release (29/4/26).....	3
3	Previous releases .....	3
3.1	12.1.1 (18/3/26) .....	3
3.2	12.1.0 (12/2/26) .....	3
3.3	11.17.0 (9/12/25) .....	3
3.4	11.16.4 (22/10/25) .....	3
3.5	11.16.3 (17/7/25) .....	4
3.6	11.16.2 (3/6/25) .....	4
3.7	11.16.1 (12/5/25) .....	4
3.8	11.16.0 (7/5/25) .....	4
3.9	11.15.10 (26/11/24).....	4
3.10	11.15.9 (6/11/24) .....	4
3.11	11.15.7 (9/11/24) .....	4
3.12	11.15.6 (25/9/24) .....	5
3.13	11.15.5 (10/9/24) .....	5
3.14	11.15.4 (23/8/24) .....	5
3.15	11.15.3 (18/7/24) .....	5
3.16	11.15.2 (17/6/24) .....	5
3.17	11.15.1 (12/6/24) .....	5

## I OVERVIEW

This document details IRIS USB Reflasher changes from software Version 12.1.1 to Version 13.0.0.

Please note – installing this release may not remove previous releases of the IRIS USB Reflasher. To prevent this, it is recommended that earlier version(s) of the IRIS USB Reflasher are uninstalled before this new version is installed.

Also note that this release installs a USB driver called 'AddSecure'. This driver is shared with the IRIS Toolbox App, so if you install this version of USB Reflasher, you must install the latest IRIS Toolbox App as well.

## 2 CHANGES IN THIS RELEASE (29/4/26)

ID	Details
<b>T56210</b>	Updated all IRIS and EDGE except TDA74xx-4 to v4.28.1.21898.

## 3 PREVIOUS RELEASES

### 3.1 12.1.1 (18/3/26)

ID	Details
<b>T54374</b>	Resolve a problem where IRIS4xxNG terminals were reflashed with TDA74xxNG software.
<b>T53693</b>	Update code signing certificate.

### 3.2 12.1.0 (12/2/26)

ID	Details
<b>T51505</b>	Updated all IRIS and EDGE except TDA74xx-4 to v4.28.0.17757.

### 3.3 11.17.0 (9/12/25)

ID	Details
<b>T51505</b>	Updated all IRIS and EDGE except TDA74xx-4 to v4.27.0.14153.

### 3.4 11.16.4 (22/10/25)

ID	Details
<b>T50174</b>	Updated provisioned terminals (DS2300, VS5000, VS5300, IRIS-4 440GC) to v4.25.1.11817.

### 3.5 11.16.3 (17/7/25)

ID	Details
<b>T47662</b>	Updated all except TDA74xx-4 to v4.25.0.6755.

### 3.6 11.16.2 (3/6/25)

ID	Details
<b>T47384</b>	Updated EDGE DS2220/IRIS-4 50, IRIS-4 160, IRIS-4 2xx, IRIS-4 4xx (not 440GC), IRIS-4 6xx, TDA14xx to 4.24.4.4837.

### 3.7 11.16.1 (12/5/25)

ID	Details
<b>T46968</b>	Updated EDGE DS2220/IRIS-4 50, IRIS-4 160, IRIS-4 2xx, IRIS-4 4xx (not 440GC), IRIS-4 6xx, TDA14xx to 4.24.3.3365.

### 3.8 11.16.0 (7/5/25)

ID	Details
<b>T43694</b>	Updated EDGE DS2220/IRIS-4 50, IRIS-4 160, IRIS-4 2xx, IRIS-4 4xx (not 440GC), IRIS-4 6xx, TDA14xx to 4.24.1.3365.

### 3.9 11.15.10 (26/11/24)

ID	Details
<b>T43694</b>	Updated all terminals except TDA74xx-4 to 4.23.2.61592.

### 3.10 11.15.9 (6/11/24)

ID	Details
<b>T43161</b>	Updated all terminals except TDA74xx-4 to 4.23.1.60438.

### 3.11 11.15.7 (9/11/24)

ID	Details
<b>T42537</b>	Updated all terminals except EDGE DS2320, EDGE VS5000, EDGE VS5300 and TDA74xx-4 to 4.21.8.58963.

### 3.12 11.15.6 (25/9/24)

ID	Details
<b>T42352</b>	Updated EDGE (DS2300, VS5000, VS5300) to 4.22.1.57647.

### 3.13 11.15.5 (10/9/24)

ID	Details
<b>T41912</b>	Updated EDGE (DS2300, VS5000, VS5300) to 4.22.0.56979.

### 3.14 11.15.4 (23/8/24)

ID	Details
<b>T41371</b>	Updated all EDGE, IRIS-4, GTxx-4 and TDA14xx-4 models, but not TDA74xx-4 to V4.21.2.55626.

### 3.15 11.15.3 (18/7/24)

ID	Details
<b>T40505</b>	Updated all EDGE, IRIS-4, GTxx-4 and TDA14xx-4 models, but not TDA74xx-4 to V4.21.1.53288..

### 3.16 11.15.2 (17/6/24)

ID	Details
<b>T39743</b>	Updated EDGE DS2300 and EDGE VS5300 to V4.21.0.51723.

### 3.17 11.15.1 (12/6/24)

ID	Details
<b>T39635</b>	Update with Edge VS5000 Version 4.17.7.
<b>T39649</b>	Resolve an issue whereby terminals with a 3-part version string (e.g. NG terminals) do not get reflashed.

