

IRIS USB Reflasher

Software 11.16.0

Table of Contents

1 Overview3

2 Changes in this release (7/5/25).....3

3 Previous releases3

3.1 11.15.10 (26/11/24)3

3.2 11.15.9 (6/11/24)3

3.3 11.15.7 (9/11/24)3

3.4 11.15.6 (25/9/24)3

3.5 11.15.5 (10/9/24)4

3.6 11.15.4 (23/8/24)4

3.7 11.15.3 (18/7/24)4

3.8 11.15.2 (17/6/24)4

3.9 11.15.1 (12/6/24)4

I OVERVIEW

This document details IRIS USB Reflasher changes from software Version 11.15.10 to Version 11.16.0.

Please note – installing this release may not remove previous releases of the IRIS USB Reflasher. To prevent this, it is recommended that earlier version(s) of the IRIS USB Reflasher are uninstalled before this new version is installed.

Also note that this release installs a new USB driver called 'AddSecure'. This driver is shared with the IRIS Toolbox App, so if you install this version of USB Reflasher, you must install the latest IRIS Toolbox App as well.

2 CHANGES IN THIS RELEASE (7/5/25)

ID	Details
	Updated EDGE DS2220/IRIS-4 50, IRIS-4 160, IRIS-4 2xx, IRIS-4 4xx (not 440GC), IRIS-4 6xx, TDA14xx to 4.24.1.3365.

3 PREVIOUS RELEASES

3.1 11.15.10 (26/11/24)

ID	Details
T43694	Updated all terminals except TDA74xx-4 to 4.23.2.61592.

3.2 11.15.9 (6/11/24)

ID	Details
T43161	Updated all terminals except TDA74xx-4 to 4.23.1.60438.

3.3 11.15.7 (9/11/24)

ID	Details
T42537	Updated all terminals except EDGE DS2320, EDGE VS5000, EDGE VS5300 and TDA74xx-4 to 4.21.8.58963.

3.4 11.15.6 (25/9/24)

ID	Details
T42352	Updated EDGE (DS2300, VS5000, VS5300) to 4.22.1.57647.

3.5 11.15.5 (10/9/24)

ID	Details
T41912	Updated EDGE (DS2300, VS5000, VS5300) to 4.22.0.56979.

3.6 11.15.4 (23/8/24)

ID	Details
T41371	Updated all EDGE, IRIS-4, GTxx-4 and TDA14xx-4 models, but not TDA74xx-4 to V4.21.2.55626.

3.7 11.15.3 (18/7/24)

ID	Details
T40505	Updated all EDGE, IRIS-4, GTxx-4 and TDA14xx-4 models, but not TDA74xx-4 to V4.21.1.53288..

3.8 11.15.2 (17/6/24)

ID	Details
T39743	Updated EDGE DS2300 and EDGE VS5300 to V4.21.0.51723.

3.9 11.15.1 (12/6/24)

ID	Details
T39635	Update with Edge VS5000 Version 4.17.7.
T39649	Resolve an issue whereby terminals with a 3-part version string (e.g. NG terminals) do not get reflashed.